

ICC-ES Evaluation Report

ESR-3941

Reissued August 2023	This report also contains:
Revised May 2025	- City of LA Supplement
Subject to renewal August 2025	- CA Supplement with DSA and OSHPD

ICC-ES Evaluation Reports are not to be construed as representing aesthetics or any other attributes not specifically addressed, nor are they to be construed as an endorsement of the subject of the report or a recommendation for its use. There is no warranty by ICC Evaluation Service, LLC, express or implied, as to any finding or other matter in this report, or as to any product covered by the report.

Copyright © 2025 ICC Evaluation Service, LLC. All rights reserved.

DIVISION: 09 00 00— FINISHES Section: 09 22 26— Suspension Systems	REPORT HOLDER: CERTAINTEED CEILINGS CORPORATION ADDITIONAL LISTEE: BAILEY METAL PRODUCTS LIMITED	EVALUATION SUBJECT: QUICKSPAN [™] LOCKING DRYWALL SYSTEM (LDS)	
---	--	--	--

1.0 EVALUATION SCOPE

Compliance with the following codes:

- 2024, 2021, 2018 and 2015 International Building Code[®] (IBC)
- 2013 Abu Dhabi International Building Code (ADIBC)[†]

[†]The ADIBC is based on the 2009 IBC. 2009 IBC code sections are the same sections in the ADIBC.

Property evaluated:

Structural

2.0 USES

The QuickSpan[™] locking drywall system described in this report is used as a ceiling framing system for screwattached gypsum panel products in interior applications, in nonfire-resistance-rated construction.

3.0 DESCRIPTION

3.1 General:

The QuickSpan[™] locking drywall system is a ceiling framing system that extends from wall to wall, and provides support for screw-attached gypsum boards. The framing system consists of tees, locking channels and when necessary, support clips. The tees extend from wall to wall, and are supported by locking channels that are attached to gypsum wallboard–faced steel wall framing. The tees can also be used as perpendicular members in conjunction with support clips.

3.2 Components:

3.2.1 QuickSpan[™] Tee: The QuickSPAN[™] (QST) tee has an inverted T-shape, a double rotary-stitched web and a knurled bottom flange. The steel used to form the tee complies with ASTM A653 Commercial Steel (CS) Type B, having mechanical properties complying with the manufacturer's specifications and has a minimum G40 galvanization coating designation. <u>Table 1</u> and <u>Figure 1</u> specify the part numbers, dimensions and lengths.

3.2.2 QuickSpan[™] Locking Channel: The locking channel (QSLC) is made from steel complying with ASTM A653 Commercial Steel (CS) Type B, having mechanical properties complying with the manufacturer's specifications and has a minimum G40 galvanization coating designation. The locking channel has a hybrid CV shape configuration, locking and locating the top of the tee and securing the bottom flange on one side.



The bottom is knurled and is 1.562-inch (40 mm) wide. The back side is also knurled and the height is 1.75-inch (44 mm). The inside height of the channel from bottom to the top locking slot is 1.5-inch (38 mm). Table 1 and Figure 1 specify the part numbers, dimensions and length.

3.2.3 QuickSpan Support Clip: The support clip (QSSC1) is made from steel complying with ASTM A653 Commercial Steel (CS) Type B, having mechanical properties complying with the manufacturer's specifications and has a minimum G40 galvanization coating designation. The support clip has a U-shape profile to positively attach to QuickSpan tees and locking tabs on the upper sections to connect to a perpendicular QuickSpan tee. <u>Table 1</u> and <u>Figure 1</u> specify the part numbers and dimensions.

3.2.4 Gypsum Board: Gypsum panel products must comply with ASTM C36 or C1396, and must have a maximum thickness of $\frac{5}{8}$ inch (15.9 mm) and a maximum weight of 2.5 pounds per square foot (12.3 kg/m²).

3.2.5 Screws: Screws used to fasten locking channels to framing must be No. 6 by 1¹/₄-inch-long (32 mm), fine-thread Type S, steel-framing, wafer head, self-drilling screws complying with ASTM C1002 or SAE J78, and must be recognized in a current ICC-ES evaluation report. Screws used to fasten support clips must be No. 7 sharp point wafer-head screws.

4.0 DESIGN AND INSTALLATION

4.1 Design:

The locking drywall system is designed to support up to two layers of ${}^{5}/_{8}$ -inch-thick (15.9 mm) gypsum board having a maximum weight of 5.0 psf (22.6 kg/m²). Since the QuickSpan LDS consists of gypsum boards screwed to suspended framing members, and the ceiling is supported on one level extending between laterally braced walls, the QuickSpan LDS is exempt from the lateral load design requirements of ASTM E580 (for the 2024 IBC and ASCE 7-22; for the 2021 IBC and ASCE 7-16 including Supplement #1 and 2018 IBC and ASCE 7-16); and (2015 IBC and ASCE 7-10). Therefore, the QuickSpan LDS is not subject to the requirements for seismic design loads, as required under Chapter 13 of ASCE 7.

4.2 Installation:

4.2.1 General: The ceiling system must be installed in accordance with this report, approved construction documents specifying the QuickSpan LDS system and the manufacturer's published installation instructions.

4.2.2 QuickSpan[™] Locking Channel: The locking channel must be screw-attached to minimum No. 25 gage steel wall studs spaced at a maximum spacing of 24 inches (610 mm) on center, with one No. 6 screw described in Section 3.2.5.

4.2.3 QuickSpan[™] Tee: QuickSpan tee must be installed to span between locking channels. The tees must be cut within ¹/₈-inch (3.2 mm) of the vertical locking channel leg, and both ends must be fixed in the locking channel slots and tabs at the bottom flange. QuickSpan tee must be spaced as shown in <u>Tables 2</u>, 3, 4 and 5 for the applicable span, and leveled to within ¹/₄ inch in 10 feet (6.4 mm in 3048 mm). QuickSpan Tees used as perpendicular support members may be spliced by using an inverted QuickSpan Tee with a minimum length of 16 inches (8 inches at each side of the splice). The splice tee must be attached to the QuickSpan tee using minimum of eight No. 7 sharp point wafer-head screws (using a minimum of four screws on each side of the splice).

4.2.4 QuickSpan[™] **Support Clip:** When necessary, the QuickSpan tees must be positively attached using the QuickSpan Support Clips by fastening to the flange of a perpendicular QuickSpan tee support. Two No. 7 sharp point wafer-head screws are used to connect the upper part of the clip to the bottom flange of the QuickSpan tee support. Hanger wire spacing of QuickSpan support tee using the QuickSpan Support Clip must not exceed the spacing and loading conditions shown in <u>Table 7</u>. The QuickSpan Tees supporting the gypsum board and connected to the perpendicular QuickSpan tee and support clip must comply with the design loads in <u>Tables 2</u>, 3, 4, 5 and 6. Hanger wire must be minimum No. 12 gage galvanized, soft-annealed, mild steel wire and installed to the QuickSpan support tee and to the support above such that the wire loops are tightly wrapped and sharply bent to prevent any vertical movement or rotation of the member within the loops. The wire must be wrapped around itself a minimum of three full turns (360 degrees each) within a 3-inch length.

4.2.5 Gypsum Board Attachment: Maximum ⁵/₈-inch-thick gypsum board must be installed and fastened to the locking drywall system (tees and channel) in accordance with IBC Section 2508.

4.2.6 Lighting Fixtures: Lighting fixtures, when used, must be independently supported by the building structure.

5.0 CONDITIONS OF USE:

The QuickSpan[™] locking drywall system described in this report complies with, or is a suitable alternative to what is specified in, those codes listed in Section 1.0 of this report, subject to the following conditions:

- **5.1** The ceiling framing members must be fabricated in accordance with this report, and the locking drywall system with gypsum board must be installed in accordance with, this report, the approved construction documents and the manufacturer's published installation instructions. In the event of a conflict, the most restrictive requirement governs.
- **5.2** The connection of the ceiling framing system to supporting construction has not been evaluated and is outside the scope of this report. The code official must approve the floor, wall and/or roof construction supporting the ceiling system.
- 5.3 Installation is limited to dry, interior conditions.
- **5.4** The ceiling system must be designed for seismic loads in accordance with Chapter 13 of ASCE 7. The documents must be prepared by a registered design professional where required by statutes of the jurisdiction in which the project is to be constructed.
- **5.5** Where required by the building official, a statement of special inspection must be provided for use in Seismic Design Categories D, E and F as required under the 2024, 2021, 2018 and 2015 IBC Section 1704.3.2, as applicable.
- **5.6** Structural calculations for members and connections, including laterally braced walls, that are outside the scope of this report must be submitted to the code official at the time of permit application. The calculations must be prepared by a registered professional where required by the statutes of the jurisdiction in which the project is to be constructed.
- **5.7** The ceiling system is limited to ceilings not considered accessible in accordance with Item 30 (2024 IBC), Item 29 (2021 IBC) or Item 28 (2018 and 2015 IBC) of IBC Table 1607.1.

6.0 EVIDENCE SUBMITTED

- **6.1** Data in accordance with portions of the ICC-ES Acceptance Criteria for Suspended Ceiling Framing Systems (AC368), dated February 2024 (editorially revised August 2024).
- **6.2** Screw penetration test data in accordance with ASTM C645.

7.0 IDENTIFICATION

- **7.1** The ICC-ES mark of conformity, electronic labeling, or the evaluation report number (ICC-ES ESR-3941) along with the name, registered trademark, or registered logo of the report holder (Certainteed Ceilings Corporation or Bailey Metal Products Limited) must be included in the product label.
- **7.2** Cartons of framing members are identified with the name of Certainteed Ceilings Corporation or Bailey Metal Products Limited; the part number; and the evaluation report number (ESR-3941).
- **7.3** The report holder's contact information is the following:

CERTAINTEED CEILINGS CORPORATION 20 MOORES ROAD MALVERN, PENNSYLVANIA 19355 (610) 651-5806 www.certainteed.com ceilingstechnicalservices@certainteed.com

7.4 The Additional Listee's contact information is the following:

BAILEY METAL PRODUCTS LIMITED 1 CALDARI ROAD CONCORD, ONTARIO, L4K 3ZP CANADA (905) 738-9267 Info@bmp-group.com www.bmp-group.com

TABLE 1—DESCRIPTION OF FRAMING SYSTEM COMPONENTS

PART NUMBER ¹	MINIMUM BASE-METAL THICKNESS (inches)	LENGTH (inches)
	QuickSpan [™] Locking Channel	
QSLC12-14-20	0.0198	144
	QuickSpan [™] Tee	
QST6-13-20		72
QST8-13-20		96
QST10-13-20	0.0108	120
QST12-13-20	0.0198	144
QST14-13-20		168
QST16-13-20		192
QuickSpan [™] Support Clip		
QSSC1	0.0324"	

For **SI:** 1 inch = 25.4 mm.

¹ Part numbers for Bailey Metal Products are designated with the following: BMP-Part Number in <u>Table 1</u>. For example, BMP-QSLC12-14-20.

TABLE 2—MAXIMUM SPAN OF QuickSpan[™] TEE FOR LOAD OF 5.0 lb/ft² (24.4 kg/m²)¹

QuickSpan [™] TEE Spacing (inches, o.c.)	Maximum Span (inches)
8	107.7
16	82.8
24	72.3

For **SI:** 1 inch = 25.4 mm.

¹Installation must comply with Section 4.2 of this report. The gypsum board must be screw-fastened to each tee at the designated tee spacing in the table.

TABLE 3—MAXIMUM SPAN OF QuickSpan[™] TEE FOR LOAD OF 2.5 lb/ft² (12.2 kg/m²)¹

QuickSpan [™] TEE Spacing (inches, o.c.)	Maximum Span (inches)
8	135.6
16	107.7
24	91.1

For **SI:** 1 inch = 25.4 mm.

¹Installation must comply with Section 4.2 of this report. The gypsum board must be screw-fastened to each tee at the designated tee spacing in the table.

TABLE 4—MAXIMUM SPAN OF QuickSpan [™] TEE FOR LOAD OF 2.0 lb/f	ft² (9	9.76 kg/m	²) ¹
---	--------	-----------	-----------------------------

QuickSpan [™] TEE Spacing (inches, o.c.)	Maximum Span (inches)
8	152.3
16	116.0
24	98.2

For **SI:** 1 inch = 25.4 mm.

 $^1 lnstallation must comply with Section 4.2 of this report. The gypsum board must be screw-fastened to each tee at the designated tee spacing in the table.$

FABLE 5—MAXIMUM SPAN OF QuickSpan	TEE FOR LOAD OF	1.4 lb/ft ² (6.8 kg/m ²) ¹
-----------------------------------	-----------------	--

QuickSpan [™] TEE Spacing (inches, o.c.)	Maximum Span (inches)
8	168.0
16	130.6
24	114.1

For **SI:** 1 inch = 25.4 mm.

¹Installation must comply with Section 4.2 of this report. The gypsum board must be screw-fastened to each tee at the designated tee spacing in the table.

SPAN (INCHES)	DESIGN LOAD
48	33.86
54	24.02
60	17.51
66	13.16
72	10.13
78	7.97
84	6.38
90	5.19
96	4.28
102	3.60
108	3.31
114	2.81
120	2.41
126	2.08
132	1.81
144	1.51
168	1 03

For **SI**: 1 inch = 25.4 mm, 1 plf=14.9 N/m.

 1 Installation must comply with Section 4.2 of this report and as shown in <u>Table 2, 3, 4</u> and <u>5</u> above.

TABLE 7—HANGER WIRE SPACING (INCHES) FOR QuickSpan™	
PERPENDICULAR SUPPORT TEE AND SUPPORT CLIP ¹	

Unsupported Span ² (ft)	Ceiling Load (psf)			
	5 psf	2.5 psf	2.0 psf	1.4 psf
3.5	60.0	75.6	78.0	78.0
4	57.4	72.3	78.0	78.0
4.5	55.2	69.5	74.9	78.0
5	53.3	67.1	72.3	78.0
5.5	51.6	65.0	70.0	78.0
6	50.1	63.2	68.0	76.6
6.5	48.8	61.5	66.2	74.6
7	47.6	60.0	64.6	72.8
7.5	46.5	58.6	63.2	71.1
8	45.5	57.4	61.8	69.6

For **SI:** 1 inch= 25.4 mm, 1 feet = 305 mm, 1 psf = 4.9 kg/m². ¹Installation must comply with Section 4.2.4 of this report and as shown in <u>Tables 2, 3, 4, 5</u> and <u>6</u>. ²Unsupported span is equal to the distance measured between locking channels and the perpendicular QuickSpan tee support.



FIGURE 1—QuickSpan[™] LOCKING DRYWALL SYSTEM COMPONENTS (QSLC, QST and QSSC1)



ICC-ES Evaluation Report

ESR-3941 City of LA Supplement

Reissued August 2023

Revised May 2025

This report is subject to renewal August 2025.

www.icc-es.org | (800) 423-6587 | (562) 699-0543

A Subsidiary of the International Code Council®

DIVISION: 09 00 00—FINISHES Section: 09 22 26—Suspension Systems

REPORT HOLDER:

CERTAINTEED CEILINGS CORPORATION

EVALUATION SUBJECT:

QUICKSPAN[™] LOCKING DRYWALL SYSTEM (LDS)

1.0 REPORT PURPOSE AND SCOPE

Purpose:

The purpose of this evaluation report supplement is to indicate that the QuickSpan[™] Locking Drywall Systems, described in ICC-ES evaluation report <u>ESR-3941</u>, have also been evaluated for compliance with the code noted below as adopted by the Los Angeles Department of Building and Safety (LADBS).

Applicable code edition:

2023 City of Los Angeles Building Code (LABC)

2.0 CONCLUSIONS

The QuickSpan[™] Locking Drywall Systems, described in Sections 2.0 through 7.0 of the evaluation report <u>ESR-3941</u> comply with the LABC Chapters 8, 16 and 25, and are subjected to the conditions of use described in this supplement.

3.0 CONDITIONS OF USE

The QuickSpan[™] Locking Drywall Systems described in this evaluation report must comply with all of the following conditions:

- All applicable sections in the evaluation report ESR-3941.
- The design, installation, conditions of use and identification of the QuickSpan[™] Locking Drywall Systems are in accordance with the 2021 *International Building Code*[®] (IBC) provisions noted in the evaluation report <u>ESR-3941</u>.
- The design, installation and inspection are in accordance with additional requirements of LABC Chapters 16 and 17, as applicable.
- Main runners shall be identified by indentation or by nontransferable decal with letters not less than ¹/₄-inch high, and shall include the company name, runner designation and load rating.

This supplement expires concurrently with the evaluation report, reissued August 2023 and revised May 2025.





ICC-ES Evaluation Report

ESR-3941 CA Supplement

w/ DSA and OSHPD

Reissued August 2023

Revised May 2025

This report is subject to renewal August 2025.

www.icc-es.org | (800) 423-6587 | (562) 699-0543

A Subsidiary of the International Code Council®

DIVISION: 09 00 00—FINISHES Section: 09 22 26—Suspension Systems

REPORT HOLDER:

CERTAINTEED CEILINGS CORPORATION

EVALUATION SUBJECT:

QUICKSPAN[™] LOCKING DRYWALL SYSTEM (LDS)

1.0 REPORT PURPOSE AND SCOPE

Purpose:

The purpose of this evaluation report supplement is to indicate that QuickSPAN[™] Locking Drywall System, described in ICC-ES evaluation report ESR-3941, has also been evaluated for compliance with the code noted below.

Applicable code edition:

2022 California Building Code (CBC)

For evaluation of applicable chapters adopted by the <u>California Office of Statewide Health Planning and Development</u> (OSHPD) AKA: California Department of Health Care Access and Information (HCAI) and the Division of State Architects (DSA), see Sections 2.1.1 and 2.1.2 below.

2.0 CONCLUSIONS

2.1 CBC:

The QuickSPAN[™] Locking Drywall System, described in Sections 2.0 through 7.0 of the evaluation report ESR-3941, complies with CBC Chapters 8, 16, 17, and 25, as applicable, provided the design and installation are in accordance with the 2021 *International Building Code*[®] (IBC) provisions noted in the evaluation report and the additional requirements of CBC Chapters 8, 16, 17 and 25, as applicable.

2.1.1 OSHPD:

The QuickSPAN[™] Locking Drywall System, described in Sections 2.0 through 7.0 of the evaluation report ESR-3941, complies with CBC Chapters 8, 16, 17 and 25, with applicable amendments, and CBC Chapters 16A and 17A, provided the design and installation are in accordance with the 2021 *International Building Code*[®] (IBC) provisions noted in the evaluation report and the additional requirements in Sections 2.1.1.1 and 2.1.1.2 of this supplement:

2.1.1.1 Conditions of Use:

- 1. All loads applied shall be determined by a registered structural engineer and shall comply with applicable loads from CBC Chapter 16 and its amendments, and Chapter 16A.
- 2. Design and installation shall comply with the requirements of OSHPD Preapproved Details (OPD) OPD-0003-13.

2.1.1.2 Special Inspection Requirements:

- 1. Periodic special inspection is required in accordance with Section 1705A.12.5 of CBC [OSHPD 1 and 4]
- Where gypsum wallboard is used in suspended ceiling installations, additional inspection shall be in accordance with CBC Section 2503.2 [OSHPD 1, 1R, 2, 4, and 5].

ICC-ES Evaluation Reports are not to be construed as representing aesthetics or any other attributes not specifically addressed, nor are they to be construed as an endorsement of the subject of the report or a recommendation for its use. There is no warranty by ICC Evaluation Service, LLC, express or implied, as to any finding or other matter in this report, or as to any product covered by the report.



2.1.2 DSA:

The QuickSPAN[™] Locking Drywall System, described in Sections 2.0 through 7.0 of the evaluation report ESR-3941, complies with CBC Chapters 8, 16, and 25, with applicable amendments, and CBC Chapters 16A and 17A, provided the design and installation are in accordance with the 2021 *International Building Code*[®] (IBC) provisions noted in the evaluation report and the additional requirements in Sections 2.1.2.1 and 2.1.2.2 of this supplement:

2.1.2.1 Conditions of Use:

- 1. All loads applied shall be determined by a registered structural engineer and shall comply with applicable loads from CBC Chapter 16 and its amendments, and Chapter 16A.
- 2. Design and installation shall comply with the requirements of DSA Interpretation of Regulations (IR) DSA IR 25-3.13.

2.1.2.2 Special Inspection Requirements:

- 1. Periodic special inspection is required in accordance with Section 1705A.12.5 of CBC [DSA-SS and DSA-SS/CC]
- 2. Where gypsum wallboard is used in suspended ceiling installations, additional inspection shall be in accordance with CBC Section 2503.2 [DSA-SS and DSA-SS/CC].

This supplement expires concurrently with the evaluation report, reissued August 2023 and revised May 2025.